4.2.2 Town End


The Town End Character Area characterises much of the building eras of Walsall, covering some of the Victorian industrial precincts of Walsall, demonstrating the leather making and metal working heritage of the town; to the 20th Century clearance with a number of open areas of land; to the mid 20th Century developments such as the Ring Road and associated office buildings, to the more recent developments of large scale shopping complexes and educational Institutions. Along with this there are pockets of housing development from the Victorian terraces and associated workshops along Station Street, to the more modern housing developments and cul-de-sacs present in Saw Mill Close.


The area also demonstrates the history of transport in Walsall, with evidence of laneways and carriageway entrances for horse and cart, and use of the canal network with the wharf and wharf buildings still present. The railway and the move towards vehicular transport and connectivity with the formation of the ring road and the need for large car parking areas to cater for today's commuter demands are also present with in this area.

Building form and scale varies greatly throughout this area and is related to their era with a haphazard of building types and styles. Victorian buildings in the character area generally have no setback from the street and range in height from 2-3 storeys and typically of brick finish and construction. Although in some areas such as Station Street, the Victorian townscape is maintained, in other areas such as the Leather Museum and Wisemore House, the buildings stand isolated amongst modern office and retail facilities as well as the ring road and car parking facilities.


The more modern developments such as office buildings, art gallery and educational college are large buildings normally setback from the street frontage and have a much larger scale and height which act as focal points and landmarks throughout the Town. Design and construction are with modern building materials of concrete, typically clad and rendered along with large areas of car parking and the introduction of multi-storey car parking areas.

4.2.2.1 Stafford Street (North)






The area retains its historic layout and much of its 19th century development and therefore is relatively sensitive, however, as buildings are in poor condition and have been insensitively altered the sensitivity is lessened to some degree.



4.2.2.2 Wisemore




Predominant materials: Traditional buildings are constructed in brick or are rendered (the museum and Wisemore House respectively). Welsh slates roof these buildings. The wider pallet of materials across the area comprise sand faced brick, brown brick, exposed concrete framing, and a variety of cladding systems. Most cladding options are utilitarian and functional and comprise a ribbed or corrugated finish. The roof of these buildings are largely not visible. Map 1876 Positive characteristics: The museum is an excellent example of Black Country workshop construction and is located in a prominent location affording good townscape merit. Wisemore house as a listed building is a significant piece of architecture within the area and comprises a hansom building of significant interest. Negative characteristics: Map 1914 The unplanned arrangement of buildings along with the degree of open space, servicing, hard standing, car parking and wasteland results in a disparate townscape of piecemeal construction. Boundaries are marked by fencing which adds a further layer of ad hoc management to the pattern of development. The condition and appearance of many buildings is of poor quality and utilitarian affordability. There is no prevailing building material or design and as such the area is a collection of unkempt sheds and units. Statement of significance: Map 1977 The area contains some exceptional examples of domestic and commercial buildings from the 19th century's industrial period. Sensitivity: 4


Walsall Council 2015

The area contains two important historic buildings (1) Wisemore House (Grade II listed building), and (2) the Leather Museum (traditional industrial works), other than these the area comprises poor quality building, most of which are set back from the street behind parking aprons and open yards and not contribute positively to the area.





4.2.2.3 The College



Walsall Council 2015 The building uses materials that focus on a pallet of complimentary greys. The key material towards the ring road is vertically applied standing seam metal cladding, adjacent to this is blue brick, white and grey rendering, structural glass and spandrel panels.

Map 1876

Map 1914

Positive characteristics:

Predominant materials:

The building is a good example of modern architecture that is both confident and assertive and addresses the ring road boldly.

The building sets the precedent for the scale and type of built form along the ring road and forms part of an early phase to enclose the ring road.

The building is a significant generator of activity along the northern stretch of the ring road and will facilitate future regeneration in this area.

Negative characteristics:

The building lacks activity at ground floor and has significant stretches of blank frontages towards the ring road.


Statement of significance:

A prominent site along the northern stretch of ring road that signposts the scale of new development along the northern edge of the town centre.




Sensitivity: 3


The area is fully developed with a modern building of bold confident design. The structure is visible from strategic vantage points along the ring road and across the town and therefore is sensitive, albeit not precious.



4.2.2.4 Portland Street





Walsall Council 2015 Predominant materials: The building under construction will use a combination of rain screens claddings that will reflect the pallet of materials that have been used on 100 Hatherton Street and the college building. **Positive characteristics:** Map 1876 The implementation of the commercial building on the ring road frontage will start to reinstate enclosure of the site and the ring road itself, which in conjunction with 100 Hatherton AStreet and the college is starting to complete this frontage along this key artery into the town. Negative characteristics: Map 1914 The loss of buildings and structures across an extensive swath of land which now largely plays host to self seeded trees and scrub land rather than development to replace what has been lost. Statement of significance: Map 197 A frontage along a key arteral route forming part of the towns ring road. A critical central section of a major masterplan to secure modern commercial floorspace that will support the towns economic regeneration. Sensitivity: 5 The area is devoid of building other than those being constructed along the ring road frontage. The urban grain has also disappeared and therefore the site has little sensitivity.



4.2.2.5 Saw Mill Close









Area Action Plan – Characterisation: Town End

4.2.2.6 Hatherton Street (North)




	Walsall Council 2015
Predominant materials: Tarmac and soft landscaping.	
Positive characteristics: The extensive soft landscaping which includes banking to the eastern margin provides a pleasant green space that screens the parking from the housing to the east. The trees along the boundary to Hatherton Street offer significant mitigation for this use along the western aspect.	Map 1876
Negative characteristics: The use of such a large area for parking alone impacts on Hatherton Street, creating a dead frontage with limited survailance and poor levels of activity.	Map 1914
Statement of significance: An area of car parking that predates the masterplanning of the area, but supports future growth.	Map 1977
Sensitivity: 5 The area is devoid of buildings or any reference to urban grain and is not sensitive to change.	



Opportunities: There is the possibility of a single development across the entire area, including over the existing car parking in connection with 100 Hatherton Street (stilted or otherwise).


4.2.2.7 100 Hatherton Street




Predominant materials: An innovative use of curtain wall glazing is the main material in the building and is used not only as a architectural expression that makes this building individual, but effectively screens (and works with) exposed floor plates. Coloured, tinted and etched/vinyl designs are applied differently on different elevations. The main material used to envelope areas of masonry is white render with complimentary areas of controlled fritted panelling to align with gazed areas. Positive characteristics: Map 1876 A building of exceptional modern design that comprises dynamic architectural form with a unique personality. The activity of the building is visible and provides substantial activity out onto the streets and surrounding courtyard areas. Whilst large, the building is of a human scale with spaces, enclosed by the buildings form and enveloped by its landscape. Negative characteristics: Map 1914 The building has an unresolved relationship with the land to the east, comprising open landscaping between the ring road and the housing estate set back behind the Queen Mary's School. Statement of significance: Map 197 The building forms a dramatic start to the main section of the northern stretch of the towns ring road at the rise of the hill from the Arboretum. The building as such is a gateway from the east to this principal section of road. Sensitivity:

Walsall Council 2015


The area is fully developed with a modern building of bold confident design. The structure is visible from strategic vantage points along the ring road and across the town and therefore is sensitive, albeit not precious.



4.2.2.8 Littleton Street




Predominant materials:	and the second sec	
Tarmac, granite sets and concrete flags.		
Positive characteristics:	Map 1876	
A number of established trees and some improved highway linkages.		
Negative characteristics:	Map 1914	
Dominated by large highway routes, junctions and gyratories that make pedestrian movement slow and difficult. A significant section of the ring road where there is no development, with the characteristics of a piecemeal planning process. Significant frontages of the area comprise the rear of buildings and their domestic servicing arrangements.		
Statement of significance:	Map 1977	
A major double frontage onto the ring road where there is no enclosure on either side of the street.		
Sensitivity: 5		
The area is absent of any buildings and exposes the rear elevations of buildings on adjacent sites, it is not sensitive to change.		




Opportunities: There are opportunities to develop the area either side of the ring road, with frontages through to Stafford Street (to the south) and through to the Wisemore area to the north. Opportunities to increase connectivity across the ring road should be taken to link the town centre proper with the college and wider 'Gigaport'.


4.2.2.9 Albert Street



Predominant materials:		
Brick is the predominant building material in the area, with arches and architectural detailing also formed of brick, suggesting the low order of buildings in this area. Roofs are clad in Welsh slate and windows are either cast iron or timber. Modern buildings are steel frame and clad in corrugated metal systems.		
Positive characteristics:		
A number of buildings relating to the leather industry have been retained and reflect the incremental development of industry in the town during the 19 th century. These building reflect the local industrial vernacular in their modest scale and simple architecture.		
Negative characteristics:		
A significant proportion of buildings are lost or laid to waste. Dereliction is rife and following clearance sites are now used only as surface level car parking. With open railings that fail to enclose the street properly.		
Statement of significance:	Map 1977	
The area has a significant length of frontage onto Littleton Street west, the northern section of the towns ring road. The area retains evidential value from the town's leather making industries during the 19 th century.		
Sensitivity: 4		
The area retains a single late 19 th century works building which boasts intended architectural design (likely due to its prominent location historically. This building, along with the Albion Tannery building on Albert Street increases sensitivity, however, much of the wider area is devoid of buildings and therefore lacks sensaticity.		




Capacity for change: There is capacity for change on the vacant site for buildings up to three-storeys in height, taking a cue from the historic buildings in the area. Strengthening street frontages will be an important consideration.




4.2.2.10 Stafford street (South)








Capacity for change: There is limited capacity for change, which is largely restricted to alterations to existing buildings, or the replacement of individual buildings is the design is considered to outweigh the existing 19th century character of the area.



Area Action Plan - Characterisation: Town End


4.2.2.11 St. Paul's Street




Predominant materials: A wide use of materials are used in this area. In the post war structures, reinforced concrete in exposed floor plates and struts is employed along with brown and red pressed bricks. The modern shed has been dressed using a variety of materials in an attempt to break down its massing. A polished aggregate blockwork is used on the southern elevation, whilst terracotta rainscreen is used across the west facing elevation. Map 1876 Positive characteristics: The new superstore and associated units along the western elevation form an animated elevation towards the newly reformed Wisemore Street and screen the railway line that runs through the site. The new shed has been dressed with higher quality materials than is normally not seen on such development and has been applied in is such a way as to create a sense of individuality across the wider elevation. Negative characteristics: Map 1914 The architecture of the post war structures is poor quality with poor quality and failing materials. The modern sheds comprise contrived architecture applied to a shed to counter its scale rather than achieve good architecture. A number of incremental open spaces that are not managed or maintained, but do not comprise developable parcels of land. Statement of significance: Map 1977 A large and dominant site, which is a destination independent of the town centre proper, much in the same way as Crown Wharf is. Sensitivity:


Walsall Council 2015

The area has been comprehensively redeveloped with a retail shed, save for the sunken railway line and 1970's office building along the eastern boundary, whist some design has been concentrated into the existing development, its retention is not critical to the future regeneration of the town, limiting sensitivity considerably.




4.2.2.12 Townend






The area comprises the ruminants of the late 19th and early 20th century, retaining a number of buildings, but also containing a number of sites hosting lost buildings and a substantial piece of highway infrastructure, isolating a small group of historic buildings in the middle of a gyratory system. The historic townscape is still detectable, however has been seriously compromised.





Capacity for change: Considering that the area sits at a confluence of roads and varying character areas and relates to none of them there is substantial capacity for change, however this should not be at the expense of historic buildings that survive.




Opportunities: There are a number of small opportunity sites with the capacity to extend up to three or four storeys in height (depending on the immediate context). The main opportunity to be sought is to strengthen this area as a node and increase connectivity from the town centre along Wisemore and Stafford Street as well as into Crown Wharf.

4.2.2.13 Art Gallery






The area contains a number of substantial historic commercial and works buildings as well as wharf buildings and also a variety of modern new build development including the art gallery, apartments, bars and hotels. It comprises a rare example in the town of where new and old architecture coexist successfully and a modern townscape has emerged with great merit in a canal setting.




4.2.2.14 Park Street (West)




Predominant materials: Brick and concrete are the primary building materials in this area of the town. The 1960's development utilises a brown brick with expressed concrete floor plates, whilst the post modern development made a far greater play on materials using red and blue pressed brick in bands and dressing the opening and coping with concrete sections. Paving is red block paving and concrete flags applied along post modernist principles and is a contemporary of this latter phase of retail construction. Positive characteristics: Map 1876 The area has a high foot fall and clearly benefits from its links with the leisure activities that have established around the canal basin and Crown Wharf (to the north). The Red Lion public house is an important historic building that has survived the redevelopment plans in this area and is one of the best examples of late 19th century gin palace architecture from the period in the town. Its eclectic mix of Jacobethan detailing and Flemish gabling is unrivalled in Walsall. Negative characteristics: Map 1914 The brutalism of the 1960's building is not a well executed work, it employs poor quality materials, introduces large sections of 'dead' frontage and has been significantly compromised by later reworking diluting its confident original design. The post modernist development shamelessly mimics the historic vernacular of the town and constitutes a contrived piece of sham architecture in a regrettable prominent location within the town. Map 1977 Statement of significance: A significant track of the high street corridor, connecting the main shopping area to Townend and the canal area and New Art Gallery. Sensitivity: 4 The area has been radically redeveloped over the last 50 years and has lost all its historic built form other than the Red


Walsall Council 2015

The area has been radically redeveloped over the last 50 years and has lost all its historic built form other than the Red Lion public house, the layout of the street and the form of the public real as the northern end of the high street terminates survives and remains important.




4.2.2.15 Station Street





The area retains much of its historic urban grain and building stock, although this has been depleted at the southern end with the loss of an important listed building.



4.2.2.16 Station

